**Ceramic End Mills** 

## **CERANIC** Corner Radius End Mills

# Ultra high productivity for nickel based heat resistant alloys






### From difficult-to-cut to easy-to-cut!


### **Generation of cutting heat**

### Feature of Ni based heat-resistant alloy

Ni based difficult-to-cut heat resistant alloys such as Inconel 718 soften at temperatures exceeding 800°C. At these temperatures, difficult-to-cut materials become easier to machine because heir bearing and tensile strengths are lowered. Ceramic end mills can work effectively at these high temperatures and self generate the heat required to soften the machined material through ultra-high feeds and speeds.



### High temperature hardness of cemented carbide and ceramic




Cemented carbide end mills are significantly reduced in strength when exceeding 800 degrees. However, the strength of ceramic end mills is not affected and therefore can be used at the high speeds and depths of cut required to generate sufficient heat to enable machining.

### **Features**




### **Cutting Performance**

Tool life comparison with Inconel 718 (HRC45) Ceramic end mill



### **Cutting efficiency 10 times**

### Tool life comparison-Inconel 718 (HRC 45)



### **Ceramic End Mills**

### Corner radius end mill, short cut length, 4-6 flute



0








Type2

DCON(h6)


Aluminum Alloy

	,		.9,			
Carbon Steel, Alloy Steel, Cast Iron	Tool Steel, Pre-Hardened Steel, Hardened Steel	Hardened Steel	Hardened Steel	Austenitic	Heat Resistant Alloy	0
( 4001/100)	(<451100)	( < 55 UDO)	(* EEUDO)	01-1-1 011	Heat Resistant Alloy	Copper





Alloy



	D0 440			
`R	DC≤12			
N	0.02 - 0.02			
î 📉	DC=6	DC=8,10	DC=12	
	- 0.008 - 0.028	- 0.009 - 0.029	- 0.011 - 0.031	
	DC=6	DC=8,10	DC=12	
h6	0 - 0.008	0 - 0.009	0 - 0.011	

- Ceramic corner radius end mill with high heat resistance.Capable of softening Ni based alloys by generating heat during machining

Order Number	DC	RE	АРМХ	LU	DN	LF	DCON	No. of Flutes	Stock	Туре
CE4SRBD0600R050	6	0.5	4.5	12	5.85	50	6	4	•	1
CE4SRBD0800R100	8	1.0	6.0	16	7.85	60	8	4	•	1
CE4SRBD1000R100	10	1.0	7.5	20	9.70	65	10	4	•	1
CE4SRBD1200R150	12	1.5	9.0	24	11.70	70	12	4	•	1
CE6SRBD0600R050	6	0.5	4.5	12	5.85	50	6	6	•	2
CE6SRBD0800R100	8	1.0	6.0	16	7.85	60	8	6	•	2
CE6SRBD1000R100	10	1.0	7.5	20	9.70	65	10	6	•	2
CE6SRBD1200R150	12	1.5	9.0	24	11.70	70	12	6	•	2

(Note 1) Never use ceramic end mills to cut titanium alloys.

Doing so will cause a risk of ignition and can be extremely dangerous.


### **RECOMMENDED CUTTING CONDITIONS**

### CE45RB

#### Shoulder Milling (mm) Inconel Work material vc (m/min) fz DC ар ae (mm/t.) ≤1.2 ≥350 ≤0.06 ≤4.5 6 8 ≥350 ≤0.06 ≤6.0 ≤1.6 10 ≥350 ≤0.06 ≤7.5 ≤2.0 12 ≥350 ≤0.06 ≤9.0 ≤2.4 Depth of DC:Dia.

Slot	Milling		(mm)
Work material	Inconel		
DC	vc (m/min)	fz (mm/t.)	ар
6	≥350	≤0.03	≤1.0
8	≥350	≤0.03	≤1.5
10	≥350	≤0.03	≤2.0
12	≥350	≤0.03	≤2.5
Depth of cut		DC	ap DC:Dia.

### CE65RB



- The outermost layer of the material may be affected by heat.
   Ensure a minimum of 0.3mm final machining allowance remains.
   The recommended ramping angle is 1.5 degree. By Shoulder milling=25% and Slot milling=50% from the cutting conditions shown.
   Gradually increase the depth of cut (Shoulder milling=ae and Slot milling=ap) starting from 0.05DC.



### **PRECAUTION**

### Requires high cutting speeds (from 350m/min to 1000m/min)

High speed cutting is required to generate the heat needed to soften materials without causing abrasion or other damage.

Cutting speeds from 350m/min to 1000m/min is recommended.

### Cutting Conditions


#### Recommendation for air blow

Do not use the coolant, it can cause thermal cracking. Air blow is not used for the purpose of cooling and should not be directed at the tool. It should be used for good chip evacuation only.




### Recommendations for continuous cuttting

Continuous cutting is highly recommended. Damage or chipping can occur during interrupted cutting.




Using maximum width and depth of cut from the start of machining may cause damage. Increase the width of cut (ae) gradually to maintain tool life.

#### **Applications**



#### Method: Down cut (climb milling)


Down cut / climb milling is highly recommended. Up cutting can be unstable.




### Tool holder recommendation - Hydraulic chuck

First recommendation for tool holding is a hydraulic chuck, second recommendation is a precision milling chuck.

Collet chucks are not suitable.





#### Do not remove the built up edge

Do not remove any built up edge manually after machining as this may cause chipping. The built up edge will be removed by the heat generated during the next cutting cycle.


### Final machining allowance of more than 0.3mm

Leave a minimum of 0.3mm finishing allowance. Machining with ceramic end mills at high temperatures can affect the outermost layer of the machined material, therefore a final machining allowance must remain.


Others

### Do not use open type machines

The chips generated during machining are at extremely high temperatures. Ensure the inside of the machine is free from any combustible materials.



Covered machining center



Covered turn mill type machine

### **APPLICATION EXAMPLES**

Cutter Body		CE6SRBD1000R100	CE6SRBD1200R150		
	Workpiece	Inconel 718	Inconel 718		
	Component	Turbine blade	Pocket component		
	Process	Blade machining	Pocket machining		
g ons	Cutting Speed (m/min)	628	700		
Cutting Conditions	Feed per Tooth (mm/t.)	0.03	0.06		
Ö	Depth of Cut (mm)	ap=0.7, ae=1.2	ap=1.5, ae=5.0		
	Cutting mode	Dry (No air blow)	Air blow		
Machine Results		Turn mill center	Vertical machining center		
		Cutting efficiency 3 times compared to carbide end miils.	Pocket milling of 100mm×100mm×10mm is completed without a prepared hole in 2min 40 seconds.		

For Your Safety

Don't handle inserts and chips without gloves. Please machine within the recommended application range and exchange expired tools with new ones in advance of breakage. Please use safety covers and wear safety glasses. When using compounded cutting oils, please take fire precautions. When attaching inserts or spare parts, please use only the correct wrench or driver. When using rotating tools, please make a trial run to check run-out, vibration and abnormal sounds etc.

### **★ MITSUBISHI MATERIALS CORPORATION**

#### MITSUBISHI MATERIALS CORPORATION

#### Overseas Sales Dept, Asian Region

KFC bldg., 8F, 1-6-1 Yokoami, Sumida-ku, Tokyo 130-0015, Japan TEL +81-3-5819-8771 FAX +81-3-5819-8774

### Overseas Sales Dept, European & American Region

KFC bldg., 8F, 1-6-1 Yokoami, Sumida-ku, Tokyo 130-0015, Japan TEL +81-3-5819-8772 FAX +81-3-5819-8774

#### http://www.mitsubishicarbide.com/en/

(Tools specifications subject to change without notice.)