
## Clamping points of cutter


(BRP Type, OCTACUT Type, BOE Type, PMF Type)

Please use the recommended HDS type set bolt, and refer to the procedure below for the correct usage.

1) Insert the HDS type set bolt into the cutter until stop.



2Line up the key way of cutter, with that of the arbor without rotating the cutter tighten up the screw.



3 Ensure that the screw is tightly screwed into place, Then assembly is complete. Please ensure that the face connecting the spindle and the arbor is in full contact.

